

## County of San Diego

CC. LAUCA

J. WILLIAM COX, M.D., Ph.D.
DIRECTOR
(619) 236-2237

DEPARTMENT OF HEALTH SERVICES
1700 PACIFIC HIGHWAY, SAN DIEGO. CALIFORNIA 92101-2417

STEVEN A. ESCOBOZA ASSISTANT DIRECTOR (619) 236-7633

ENVIRONMENTAL HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT DIVISION
P.O. BOX 85261
SAN DIEGO, CA 92138-5261
(619) 338-2222

January 12, 1990

Gerry Hardacre Environmental Resources Manager General Dynamics-Convair Division 3302 Pacific Highway San Diego, CA 92101

Dear Mr. Hardacre:

RE: Incident #89-583 / Acid Spill 12-31-89

3302 Pacific Highway-Bldg. #75.

NOTICE OF VIOLATION

This Notice of Violation is in response to the release from your facility of 10-12,000 gallons of aluminum etch solution contaminated with 5,000 gallons of sodium dichromate solution.

This incident is evidence that the current design and operation of your plating process in building #75 does not preclude the loss of hazardous materials to the environment. This constitutes a violation of Section 67120 of the California Code of Regulations (CCR), Title 22. In addition, by allowing the process tank spill containment area to be utilized for holding free liquids containing hazardous wastes, your facility is in violation of Section 66508 of Title 22, CCR.

In order to minimize the potential of another hazardous material incident and to ensure protection of the public health and safety and the environment the following actions are to be taken:

- 1) Submit a written site assessment report pursuant to Section 67145(j) of Title 22 CCR. This preliminary report must include details of the incident, a determination of the type and extent of contamination, and an assessment of actual or potential hazards to human health or the environment. This report must be submitted to this office by February 20, 1990. This case has been assigned to Darryl Fowler, of the Site Assessment and Mitigation Program of the HMMD.
- 2) Submit a preliminary hazard assessment describing the immediate and long-term corrective action your facility will pursue for improving the design and operation of the processing operation in building #75. This must be accomplished by preparing and implementing a Risk Management and Prevention Program (RMPP). The preliminary hazard assessment describing the immediate corrective action must be submitted to Pat Hoy, of the Community Response Services Program of the HMMD, by March 1, 1990. The final RMPP must be submitted by January 5, 1991.

The RMPP is designed to minimize accidents involving acutely hazardous materials, and to develop plans to respond to on-site and off-site consequences should an accident occur. Chapter 6.95 of the California Health and Safety Code defines acutely hazardous materials (AHM), as all chemicals designated by the Environmental Protection Agency (EPA) as "extremely hazardous substances". Nitric acid and hydrofluoric acid are chemicals currently on EPA's list. Please refer to the "Advanced" RMPP Guidance document prepared by the State of California Office of Emergency Services.

The Hazardous Materials Management Division is responsible for protecting the public health and safety and the environment. The documents requested are intended to minimize the hazards associated with handling hazardous materials at your facility and to correct the violations noted. Your facility is currently in violation of the law and may be subject to further legal action. Failure to correct these violations in a timely manner may be a factor in determining the course of any legal action.

If you have any questions please contact me at (619) 338-2395, Darryl Fowler or Pat Hoy at (619) 338-2222.

Sincerely,

DANIEL J. AVERA, Chief

Hazardous Materials Management Division

DJA: dmc

cc:

Nancy Riikonen-SD Metropolitan Industrial Waste Jim Munch-Regional Water Quality Control Board ¿Pat Hoy/Christina Graulau-HMMD Darryl Fowler/Ben Franklin-HMMD H#04497 File

## APPENDIX A

For the period January 1, 1987 to present, provide all original documents, reports, studies, drawings and the like, to include the original and all revisions as they relate to chemical processing, chemical handling and storage, chemical equipment and chemical materials and spills, located at General Dynamics Corporation, Convair Division, Building No. 75, Lindbergh Field Plant, San Diego, CA. These records should include, but not be limited to, the following:

- 1. All documents as they relate to inspection, maintenance, and/or repair of chemical processing equipment.
- 2. All documents, records, contracts, and the like as they relate to maintenance and/or repairs occurring to chemical tank No. 140 and all other processing equipment, storage equipment or containment equipment for chemicals.
- 3. All documents pertaining to the inspection, maintenance and/or repair of the concrete sump surrounding the area where chemical tank No. 140 is located.
- 4. All documents related to all chemical spills occurring in December 1989 at General Dynamics Corporation, Convair Division, Building No. 75, San Diego, CA.
- 5. All documents, reports of investigation, site plans, photographs, chemical test reports, worksheets and computer generated reports, which reference/relate in any way to the acid spill in December 1989, and any other hazardous spills or the discharge of hazardous materials to the sewer near or at Building No. 75.
- 6. All traveler documents or other records, related to any Government contract, indicating any parts which were processed in any way in Building No. 75.
- 7. All engineering studies, reports and the like, to include all drawings contained therein, as they relate to chemical material use and/or storage at Building No. 75.

AT 1:10 PM, SUNDAY DECEMBER 31, 1 RECEIVED A PAGE FROM STATION X TO CALL SAN DIEGO CITY FIRE DEPARTMENT. I CALLED 236-7773 AND TALKED TO . CAPTAIN LEAP OF THE CITY ITAZ MAT TEAM. HE INFORMED ME THAT CENERAL DYNAMICS EXPEXIENCED AN ACID SPILL AND THAT THE POINT LONA TREATMENT PLANT WAS TO BE NOTIFIED. THIS SPILL OCCURATED BETWEEN 9-10 AM ON DECEMBER 31. HESMO BAT THEY WERE NOT GOING TO PURSUE THE MATTER ANY FURTHER BUT CANE ME JOHN FIEZOS NO. (2720842) of Chicago Dynamics FOR MORE INFORMATION. I PALKED TO JOHN FIELDS AND ITE EXPLAINED TO ME WHAT THEY THOUGHT HAPPENED. . HE SAID THAT A 15000 GALLOW THE CONTINUING ACD ... LEAKED INTO A SUMP Which CONTAINED 5000 GALLOW . Of SUDIVIN DICLRUMATE. THE DICHROMATE SULOTION CONTAINED APPROXIMATELY 1000 PPM HEXAVALLY CHROMING. HE SMO THAT AFTER THE ACID LEAKED IT MIKED WITH ... The SODIUM OICEROMANE Which hat's NOW APPROXIMATELY 300-500 ppm HERAUALLY CLRONIUM, CORRUDED A . CARE VALUE AND EMPTHED INTO THE SANITHRY SEWER. HE THOUGHT A DOME of 12,000, ALLO AND 5000 GALLOWS of SODIUM DICGROMAN LAST. 1 TOLD 1AM I PROUGHT PAIS WAS SIGNIFICHT AND THAT I SLOWD INVESTIGATE. HE CANE ME KETT, DE ARMONDS NAME TO CALL WHEN ARRIVE AT THE PLANT, HESMO HE WAS THE PLANTS MAINTENANCE SUBLEVISOR. I PAGED MY BACK-UP JIM FRANK, INFORMED him OF THE SIRATION AND ASKED

ItIM TO MEET ME AT THE PLANT. ON ARRIVING AT THE WEST GATE, I WAS MET BY CONVAIR FRE FIGHTING TEMY. THEY WIRE ANARE of THE SPILL AND ROMARKED THAT THET DION'T KNOW WHO TO CALL THEY DIO NOT KNOW IF OTHER ACENCIES WIRE CONTACTED. I DUTTERED THE PLANT WITH KEITH DE ARMOND, ONE FIRE FIGHTER IN THE CONVAIR VAN. MR OF ARMOND ShowED ME MUDETCH THINK NO. 140 Which Consumos Anos ALC. THE TAK IS 145106 A BUILDING AND IS ADDREWY TO MYGROS OFFICE AGONE CROWNS HORIZOLDAR TANKS SURROUNDING BY A-SURIES of CONCRETE BERMS. THE PLAY AT THE DUTE WAS ShUT DOWN AND THE BURNS LOOKED CLOSAN. HE ShowED ME + ORAN Where he saw The ACID LLOAKED IMPO, I ASKED HIM HOUT THE SODING OICHROMATE ITESMO THORK WAS NO SODING DICHRUMATE. JUST THE ACID LICK SOLUTION LEAKED INTO THE SEWER. I'MFORMED HIM THAT JOHN FIELDS TOLD ME THAT SUDIVM DICHRUMATE MIXED WITH THE ACID AND LEAKED INTO THE SENIER. HE WAS ADMINIT THAT THIS DID NOT HADREN. I ASKED him IF I COULD USE his phone TO CHIC MR FIEDS. ITESADO. FINE. ON CALLING MR. FIERDS, I GARLANDO TO him About The Suring DI ChROWS ARE, HESARD SOOIUM DICGROMATE WAS INVOLVED BUT MR. DE ARMOND DIO NOT KNOW ABOUT IT. IN THE MISANDME, STATION X WAS PHEING ME. THEY SAID THE POINT LONA TREATING PLANT WANTED TO PACK TO ME- 1 CAZILO THE TRUMSMENT DIANT AND SPOKE TO AM M3515 MAT OF MR-DALE (22/6672) IN INFORMED HE THAT GENERAL DYNAMICS REPORTED A SPILL AND THAT IN ACIO SOLUTION CONSTANING HADS & HEL of APPROXIMATING 12000 9 HLLOS AND ABOUT 5000 9 HLLOWS of SODIUM DICLADUMTE WAS LOST TO THE SEWER. I TOLD HIM THAT WAS THE SAME INTORMATION TOUR FIEZOS CANEME.

MEN TALKED TO KESTA DE MANGUE AND I QUESTOURD
THE MARK OF THE PLANT ITE WAS Showing ME. IT ODN'T
APPEAR TO REFIRED WHAT JOHN FIEZOS DESCRIBED. ITE
SAID HE ONLY KNOW THAT THE NO. 140 LONKED AND
DIDN'T KNOW ANYTHING ABOUT SODIUM DICHROMATE, I
LEFT THE PLANT WITH A LOT OF CHAMBURGES OURSTONS
AND WROTE UP MY HIRT REDORT.

ON NEW YEAR'S DAY, STATION X PAGED ME AT APPROXIMATELY 11:40 AM. TORRY HARDHORE (542-7712) CHANTED TO KNOW IF I KNEW ASONT THE ACID SPILL AT GENERAL DYNAMICS, I SAID I WAS OUT TREE YESTORDAY It's port of voice trokesses STRPRISE: I TOUD WIN WHAT JOHN FILOS SAID, HE SAID WHAT REALLY HASPENED WAS " LUAS THAT ACIO LICH TANK RO. 140 CEAKED INTO THE CONCRETE BIRM, THE BURM IN NEW hAD A HOLE AND The ACID LEAKED IND THE CROWD. HE SAND PACIFIC TREASMENT WAS OUT THORE NOW PLYDING OUT WHAT THEY COULD. HE SAID THE ACID NEVER WENT 140 THE SENCE. HE ALSO STATED PLAT A "CEMENT FINISHER WOULD BE CALLED TO REPAR THE BERM, A CONTRACT TO REZING THE MEID GTCG THIK AND A CONSULTAT TO DESTORM A SITE MISSERSMENT. HE CANDIDLY REMARKED THAT NU ENVIRONMENTAL DAMAJE OCCURROS SINCE THE SOIL 15 MIKSCIAE, The ACID WAS NEWTRACED WHEN IT LOAKED.

ON REDRENAG DO WORK TUEDAY, I LEST MOSSAYS WIR DAW ARRA, CHUCK DRYAMZ, VICKY CALCAGALA AND

KEN CALVERS MOUT THE SIMMON. I, IN ADDITION, MADE A SIR ABSESSMET REFERENT TO LARRY BUDENHALLR OF THE SITE ASSESSMEN/MITICHTUN UMT. I CALLOO THE RIBIONE BOOKS, DIM MUNEY, AND THE CITY INDUSTRIAL LIMSTE, MAICY RIKOMEN AND INFORMED They of The SIMMON. COPIES OF THE HAF REDURT WERE ALSO GUE TO BEN FRANKIN OF THE THEO.

OPERATIONS UNIT.

MIKE ( ERMON 1/5/90

MOTICE OF VIOLATION



## County of San Diego

DEPARTMENT OF HEALTH SERVICES

1700 PACIFIC HIGHWAY, SAN DIEGO, CALIFORNIA 92101-2417

STEVEN A. ESCOBOZA ASSISTANT DIRECTOR (619) 236-7633

J. WILLIAM COX. M.D., Ph.D.

(619) 236-2237

ENVIRONMENTAL HEALTH SERVICES
HAZARDOUS MATERIALS MANAGEMENT DIVISION
P.O. BOX 85261
SAN DIEGO, CA 92138-5261
(619) 338-2222

January 12, 1990

Gerry Hardacre Environmental Resources Manager General Dynamics-Convair Division 3302 Pacific Highway San Diego, CA 92101

Dear Mr. Hardacre:

RE: Incident #89-583 / Acid Spill 12-31-89

3302 Pacific Highway-Bldg. #75

NOTICE OF VIOLATION

This Notice of Violation is in response to the release from your facility of 10-12,000 gallons of aluminum etch solution contaminated with 5,000 gallons of sodium dichromate solution.

This incident is evidence that the current design and operation of your plating process in building #75 does not preclude the loss of hazardous materials to the environment. This constitutes a violation of Section 67120 of the California Code of Regulations (CCR), Title 22. In addition, by allowing the process tank spill containment area to be utilized for holding free liquids containing hazardous wastes, your facility is in violation of Section 66508 of Title 22, CCR.

order to minimize the potential of another hazardous material cident and to ensure protection of the public health and safety the environment the following actions are to be taken:

CC. CLAURA

- 1) Submit a written site assessment report pursuant to Section 67145(j) of Title 22 CCR. This preliminary report must include details of the incident, a determination of the type and extent of contamination, and an assessment of actual or potential hazards to human health or the environment. This report must be submitted to this office by February 20, 1990. This case has been assigned to Darryl Fowler, of the Site Assessment and Mitigation Program of the HMMD.
- 2) Submit a preliminary hazard assessment describing the immediate and long-term corrective action your facility will pursue for improving the design and operation of the processing operation in building #75. This must be accomplished by preparing and implementing a Risk Management and Prevention Program (RMPP). The preliminary hazard assessment describing the immediate corrective action must be submitted to Pat Hoy, of the Community Response Services Program of the HMMD, by March 1, 1990. The final RMPP must be submitted by January 5, 1991.

The RMPP is designed to minimize accidents involving acutely hazardous materials, and to develop plans to respond to on-site and off-site consequences should an accident occur. Chapter 6.95 of the California Health and Safety Code defines acutely hazardous materials (AHM), as all chemicals designated by the Environmental Protection Agency (EPA) as "extremely hazardous substances". Nitric acid and hydrofluoric acid are chemicals currently on EPA's list. Please refer to the "Advanced" RMPP Guidance document prepared by the State of California Office of Emergency Services.

The Hazardous Materials Management Division is responsible for protecting the public health and safety and the environment. The documents requested are intended to minimize the hazards associated with handling hazardous materials at your facility and to correct the violations noted. Your facility is currently in violation of the law and may be subject to further legal action. Failure to correct these violations in a timely manner may be a factor in determining the course of any legal action.

If you have any questions please contact me at (619) 338-2395, Darryl Fowler or Pat Hoy at (619) 338-2222.

Singerely,

DANIEL J. AVERA, Chief

Hazardous Materials Management Division

DJA:dmc

CC: Nancy Riikonen-SD Metropolitan Industrial Waste Jim Munch-Regional Water Quality Control Board LPat Hoy/Christina Graulau-HMMD Darryl Fowler/Ben Franklin-HMMD H#04497 File

INCIDENT TYPE 028

NARRATIVE ATTACHED

HAZARDOUS MATERIALS INCIDENT RESPONSE REPORT AGENCY-REPORT # FIRE/OTHER # | SOFO # | COUNTY # | HIRT # 89-583 TOTAL TIME 3.5 + 2 12/31/89 TIME: INITIAL DISPATCH 1310 SCENE ARRIVAL 1420 RETURN HOTS \_\_\_\_\_TIME IN HOTS 3302 Pacific Highway San Diego '92101 LOCATION Street City Thom Bros: Pg/Coord. JURISDICTION: FIRE DISTRICT San Diego Fire PHONE # 236-7773

SCENE MGR INCIDENT COMMANDER RESPONDING AGENCIES (Include Contact Person on Scene): County Haz Mat Mike Vernetti J. Frank SEND BILL TO: NAME COMPANY General Dynamics/Convair CONTACT PERSON J. Fields ADDRESS 3302 Pacific Highway, San Diego PROPERTY OWNER \_\_\_\_\_\_ PHONE \_\_\_\_\_ ADDRESS HAZARDOUS MATERIALS: DESCRIPTION Acid etch tank No. 140 Nitric Acid (HNO3), HCL, Sodium Bicromate REWARKS: (Include description and action taken) Received call from Capt. Leap, San Diego Fire. General Dynamics reported an acid spill which occurred between 9:00 - 10:00 a.m. A 15000 gal acid etch tank leaked into a series of sumps which contained Sodium Bicromate. 12000 gal of Nitric Acid and 5000 gal Sodium Bicromate was lost into the sewer system. Apparently the acid corroded a gate valve in the sump causing the spill. This information was reported to me by John Fields of General Dynamics. A site investigation was made by Vernetti and Keith De Armond, Maintenance Supervisor. Point Loma Treatment Facility was advised of the spill. Persons contacted: John Field, General Dynamics 272-0842 Keith De Armond, General Dynamics 542-7742; Mr. Dale, Pcint Loma Treatment 221-6627 ADDITIONAL ACTION REQUIRED: Referral to Nancy Rikomen of City Water Utilities and to HMMD Specialist Manifest # COPIES SENT TO: ODP CITY HAZ MAT PERSON\_PREPARING REPORT: " HIRT TEAM RECOMMENDS COST RECOVERY: Mike Vernetti - HMMD |X | Yes COSTS: 5.5 x \$60.00 = \$330.00

Proposition 65 Notification #

Designated Government Employee

HAZARDOUS MATERIA	NCIDERT RESPONSE TE	INCIDENT TYPE DOR
JAN 2- 1990 HAZARDOUS MATERIA		KEPURI —
DATE 1/1/90 ·		TOTAL TIMES -
TIME: INITIAL DISPATCH SCENE AR	RIVALRETURN HO	TOTAL TIMEO_5 +  A + B  TIME IN HOIS
LOCATION 3302 Pacific Hwy Street	San Diego 92101	
JURISDICTION: FIRE DISTRICT STATE	0 T 2	Thom Bros: Pg/Coord.
SCENE MGR	Diego Fire PHONE #  INCIDENT COMMANDER	
RESPONDING AGENCIES (Include Contact Pe	rson on Scene): Cou	ntcy Haz Mac
SEND BILL TO: NAME		
	20	OBJACUS CIC
COMPANY General Dynamics/Convair ADDRESS3302 Pacific Highway, San Die	CUNTACT PER	SON J. Hardacre CORP
PROPERTY OWNER		PHONE 542-7712
ADDRESS		PHONE
HAZARDOUS MATERIALS: DESCRIPTION  Acid Etch tank No. 140  Nitric Acid (HNO <sub>3</sub> ), Hydrochloric acid (		
REMARKS: (Include description and action This is an update to Hirt Report dated Hardacre, Environmental Mgr., General Diacid etch solution spill did not go into hole in the concrete sump in the ground lost. Pacific Treatment is now pumping will be hired to perform soil sampling a contractor will repair the sump and anot tank. HE SAID SODIUM BICHROMANE WAS FIELDS SAID IT WAS.	12/31/89. 'phone con ynamics/Convair. He e o the sewer system. Reports of 7000 to out what they can. A and extent of contamin	xplained to me that the It emptied through a 12000 gallons were A private contractor nation. A cement
ADDITIONAL ACTION REQUIRED:		
Refer to SAM for follow up. Referred to Regional Board - Jim Munch 2	65-5114 Manifest #	
OPIES. SENT TO: OOP RWQCB CITY HAZ MAT		
ERSON_PREPARING REPORT: ** Mike Vernetti - HMMD	HIDT TOAL OFFI	Levy
	HIRT TEAM RECOMMENT	!
1 Proposition CC	C^STS: 0.5 x \$60.0	U = \$30.00 
Proposition 65 Notification #		i HARRELLVE ATTACHED